

Part of Thermo Fisher Scientific

The world leader in serving science

Material Safety Data Sheet

Pierce® BCA Reagents

1. Product and company identification

: Pierce® BCA Reagents

: Pierce® BCA Protein Assay Reagent B; Pierce® Micro BCA Reagent C; BCA Reagent B Synonym

: Thermo Fisher Scientific Manufacturer : Thermo Fisher Scientific Supplier Pierce Biotechnology Pierce Biotechnology

P.O. Box 117 P.O. Box 117 Rockford, IL 61105 Rockford, IL 61105 United States United States 815.968.0747 or 815.968.0747 or 800.874.3723 800.874.3723

Code : 0023224 0023224B 0023234 1856056 1859068 1859078 1862634 1862725 1879980

MSDS# : 2250 Validation date : 2/29/2012. : 2/29/2012. Print date

: MSDS Specialist Responsible name

: CHEMTREC: Material uses Refer to the instruction In case of emergency 800.424.9300 booklet for proper and **OUTSIDE US:**

intended use. Otherwise, 703.527.3887 contact supplier for specific

applications.

Product type : Liquid.

2. Hazards identification

Emergency overview

Physical state : Liquid. [Clear sparkling liquid.]

Color : Blue. Signal word : WARNING!

Hazard statements : HARMFUL IF SWALLOWED. CAUSES RESPIRATORY TRACT, EYE AND SKIN

IRRITATION. MAY CAUSE ALLERGIC SKIN REACTION. CONTAINS MATERIAL

THAT CAN CAUSE TARGET ORGAN DAMAGE.

Precautionary measures : Do not breathe vapor or mist. Do not ingest. Use only with adequate ventilation. Do not

eat, drink or smoke when using this product. Avoid contact with eyes, skin and clothing.

Keep container tightly closed. Wash thoroughly after handling.

OSHA/HCS status : This material is considered hazardous by the OSHA Hazard Communication Standard

(29 CFR 1910.1200).

: Dermal contact, Eve contact, Inhalation, Ingestion, Routes of entry

Potential acute health effects

Inhalation : Irritating to respiratory system.

Ingestion : Toxic if swallowed.

Skin : Irritating to skin. May cause sensitization by skin contact.

Eyes : Irritating to eyes.

Potential chronic health effects

2/29/2012.

Rockford II (815) 968-0747 Life Science Research PO Box 117 www.thermo.com

3747 N. Meridian Road (815) 968-7316 Fax

Pierce® BCA Reagents

2. Hazards identification

Chronic effects : Contains material that can cause target organ damage. Once sensitized, a severe

allergic reaction may occur when subsequently exposed to very low levels.

Carcinogenicity : No known significant effects or critical hazards. Mutagenicity : No known significant effects or critical hazards. Teratogenicity : No known significant effects or critical hazards. **Developmental effects** : No known significant effects or critical hazards.

Fertility effects : No known significant effects or critical hazards.

: Contains material which causes damage to the following organs: heart. **Target organs**

Contains material which may cause damage to the following organs: blood, kidneys, lungs, the nervous system, liver, upper respiratory tract.

Over-exposure signs/symptoms

Inhalation : Adverse symptoms may include the following:

respiratory tract irritation

coughing

Ingestion : No specific data.

Skin : Adverse symptoms may include the following:

redness

Eyes : Adverse symptoms may include the following:

pain or irritation watering

Medical conditions : Pre-existing skin disorders and disorders involving any other target organs mentioned in

aggravated by overthis MSDS as being at risk may be aggravated by over-exposure to this product.

exposure

See toxicological information (Section 11)

3. Composition/information on ingredients

United States

Name	CAS number	%
Copper(II) sulfate, pentahydrate (1:1:5)	7758-99-8	3 - 5

Canada

1/9

Ganada		
Name	CAS number	%
Copper(II) sulfate, pentahydrate (1:1:5)	7758-99-8	3 - 5

There are no additional ingredients present which, within the current knowledge of the supplier and in the concentrations applicable, are classified as hazardous to health or the environment and hence require reporting in this section.

4. First aid measures

Check for and remove any contact lenses. Immediately flush eyes with plenty of water Eye contact

for at least 15 minutes, occasionally lifting the upper and lower eyelids. Get medical

attention immediately

Skin contact : In case of contact, immediately flush skin with plenty of water for at least 15 minutes

while removing contaminated clothing and shoes. Wash clothing before reuse. Clean shoes thoroughly before reuse. Get medical attention immediately.

Inhalation

: Move exposed person to fresh air. If not breathing, if breathing is irregular or if respiratory arrest occurs, provide artificial respiration or oxygen by trained personnel.

Loosen tight clothing such as a collar, tie, belt or waistband. Get medical attention immediately.

2/9

2/29/2012.

Rockford II (815) 968-0747 Life Science Research PO Rox 117 www.thermo.com 3747 N. Meridian Road (815) 968-7316 Fax

4. First aid measures

Ingestion

: Wash out mouth with water. Do not induce vomiting unless directed to do so by medical personnel. Never give anything by mouth to an unconscious person. Get medical

attention immediately

Protection of first-aiders

: No action shall be taken involving any personal risk or without suitable training. If it is suspected that fumes are still present, the rescuer should wear an appropriate mask or self-contained breathing apparatus. It may be dangerous to the person providing aid to give mouth-to-mouth resuscitation. Wash contaminated clothing thoroughly with water before removing it, or wear gloves.

Notes to physician

: No specific treatment. Treat symptomatically. Contact poison treatment specialist immediately if large quantities have been ingested or inhaled.

5. Fire-fighting measures

Flammability of the product : In a fire or if heated, a pressure increase will occur and the container may burst.

Extinguishing media

Suitable

: Use an extinguishing agent suitable for the surrounding fire.

Not suitable

Special exposure hazards

: Promptly isolate the scene by removing all persons from the vicinity of the incident if there is a fire. No action shall be taken involving any personal risk or without suitable

Hazardous thermal decomposition products : Decomposition products may include the following materials:

sulfur oxides

Special protective equipment for fire-fighters : Fire-fighters should wear appropriate protective equipment and self-contained breathing apparatus (SCBA) with a full face-piece operated in positive pressure mode.

6. Accidental release measures

Personal precautions

: No action shall be taken involving any personal risk or without suitable training. Evacuate surrounding areas. Keep unnecessary and unprotected personnel from entering. Do not touch or walk through spilled material. Do not breathe vapor or mist. Provide adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Put on appropriate personal protective equipment (see Section 8).

Environmental precautions : Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers. Inform the relevant authorities if the product has caused environmental pollution (sewers, waterways, soil or air).

Methods for cleaning up

Small spill

: Stop leak if without risk. Move containers from spill area. Dilute with water and mop up if water-soluble. Alternatively, or if water-insoluble, absorb with an inert dry material and place in an appropriate waste disposal container. Dispose of via a licensed waste disposal contractor

Large spill

: Stop leak if without risk. Move containers from spill area. Approach release from upwind. Prevent entry into sewers, water courses, basements or confined areas. Wash spillages into an effluent treatment plant or proceed as follows. Contain and collect spillage with non-combustible, absorbent material e.g. sand, earth, vermiculite or diatomaceous earth and place in container for disposal according to local regulations (see section 13). Dispose of via a licensed waste disposal contractor. Contaminated absorbent material may pose the same hazard as the spilled product. Note: see section 1 for emergency contact information and section 13 for waste disposal.

www.thermo.com

Pierce® BCA Reagents

7. Handling and storage

Handling

Put on appropriate personal protective equipment (see Section 8). Eating, drinking and smoking should be prohibited in areas where this material is handled, stored and processed. Workers should wash hands and face before eating, drinking and smoking. Remove contaminated clothing and protective equipment before entering eating areas. Persons with a history of skin sensitization problems should not be employed in any process in which this product is used. Do not get in eyes or on skin or clothing. Do not breathe vapor or mist. Do not ingest. Use only with adequate ventilation. Wear appropriate respirator when ventilation is inadequate. Keep in the original container or an approved alternative made from a compatible material, kept tightly closed when not in use. Empty containers retain product residue and can be hazardous. Do not reuse

Storage

: Store between the following temperatures: 20 to 25°C (68 to 77°F). Store in accordance with local regulations. Store in original container protected from direct sunlight in a dry, cool and well-ventilated area, away from incompatible materials (see section 10) and food and drink. Keep container tightly closed and sealed until ready for use. Containers that have been opened must be carefully resealed and kept upright to prevent leakage. Do not store in unlabeled containers. Use appropriate containment to avoid environmental contamination

8. Exposure controls/personal protection

United States

Ingredient	Exposure limits
Copper(II) sulfate, pentahydrate (1:1:5)	ACGIH TLV (United States). TWA: 1 mg/m³ NIOSH REL (United States). TWA: 1 mg/m³

Canada

Occupational exposure limits		TWA (8 hours)		STEL (15 mins)		Ceiling					
Ingredient	List name	ppm	mg/m³	Other	ppm	mg/m³	Other	ppm	mg/m³	Other	Notations
Copper(II) sulfate, pentahydrate (1:1:5)	US ACGIH	-	1	-	-	-	-	-	-		

Consult local authorities for acceptable exposure limits.

procedures

Recommended monitoring : If this product contains ingredients with exposure limits, personal, workplace atmosphere or biological monitoring may be required to determine the effectiveness of the ventilation or other control measures and/or the necessity to use respiratory protective equipment.

Engineering measures

: Use only with adequate ventilation. If user operations generate dust, fumes, gas, vapor or mist, use process enclosures, local exhaust ventilation or other engineering controls to keep worker exposure to airborne contaminants below any recommended or statutory

Hygiene measures

: Wash hands, forearms and face thoroughly after handling chemical products, before eating, smoking and using the lavatory and at the end of the working period. Appropriate techniques should be used to remove potentially contaminated clothing. Contaminated work clothing should not be allowed out of the workplace. Wash contaminated clothing before reusing. Ensure that eyewash stations and safety showers are close to the workstation location.

Personal protection

Respiratory

: Use a properly fitted, air-purifying or air-fed respirator complying with an approved standard if a risk assessment indicates this is necessary. Respirator selection must be based on known or anticipated exposure levels, the hazards of the product and the safe working limits of the selected respirator.

4/9

2/29/2012. 2/29/2012. 3/9

> Rockford II (815) 968-0747 Life Science Research PO Box 117 Pierce Biotechnology Inc. 3747 N. Meridian Road (815) 968-7316 Fax

Rockford II (815) 968-0747 Life Science Research PO Rox 117 www.thermo.com Pierce Biotechnology Inc. 3747 N. Meridian Road (815) 968-7316 Fax

8. Exposure controls/personal protection

Hands

Skin

Chemical-resistant, impervious gloves complying with an approved standard should be worn at all times when handling chemical products if a risk assessment indicates this is

necessary.

Eyes

: Safety eyewear complying with an approved standard should be used when a risk assessment indicates this is necessary to avoid exposure to liquid splashes, mists or

: Personal protective equipment for the body should be selected based on the task being performed and the risks involved and should be approved by a specialist before handling

this product.

Environmental exposure

controls

: Emissions from ventilation or work process equipment should be checked to ensure they comply with the requirements of environmental protection legislation. In some cases, fume scrubbers, filters or engineering modifications to the process equipment will be

necessary to reduce emissions to acceptable levels.

9. Physical and chemical properties

Physical state : Liquid. [Clear sparkling liquid.]

Flash point : [Product does not sustain combustion.]

Color

Solubility : Easily soluble in the following materials: cold water and hot water.

10. Stability and reactivity

: The product is stable. Chemical stability Conditions to avoid : No specific data. Incompatible materials : No specific data.

Hazardous decomposition : Under normal conditions of storage and use, hazardous decomposition products should

products

not be produced.

Possibility of hazardous

reactions

: Under normal conditions of storage and use, hazardous reactions will not occur.

11. Toxicological information

United States

Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure
Copper(II) sulfate, pentahydrate (1:1:5)	LD50 Oral	Rat	300 mg/kg	-

Conclusion/Summary : Not available.

Chronic toxicity

Conclusion/Summary : Not available.

Irritation/Corrosion

Conclusion/Summary : Not available.

Sensitizer

Conclusion/Summary : Not available.

Carcinogenicity

Conclusion/Summary : Not available. **Mutagenicity**

Conclusion/Summary : Not available.

Teratogenicity

2/29/2012.

Conclusion/Summary : Not available.

Rockford II (815) 968-0747 Life Science Research PO Box 117

www.thermo.com Pierce Biotechnology Inc. 3747 N. Meridian Road (815) 968-7316 Fax

Pierce® BCA Reagents

11. Toxicological information

Reproductive toxicity

Conclusion/Summary : Not available

Canada

Acute toxicity

Product/ingredient name	Result	Species	Dose	Exposure
Copper(II) sulfate, pentahydrate (1:1:5)	LD50 Oral	Rat	300 mg/kg	-

Conclusion/Summary : Not available

Chronic toxicity

Conclusion/Summary : Not available.

Irritation/Corrosion

Conclusion/Summary Not available

Sensitizer

Conclusion/Summary : Not available.

Carcinogenicity

Conclusion/Summary : Not available.

Mutagenicity

: Not available. Conclusion/Summary

Teratogenicity

Conclusion/Summary : Not available.

Reproductive toxicity

Conclusion/Summary : Not available

12. Ecological information

Ecotoxicity : No known significant effects or critical hazards

United States

Aquatic ecotoxicity

Product/ingredient name	Result	Species	Exposure
Copper(II) sulfate, pentahydrate (1:1:5)	EC50 0.024 mg/l	Daphnia	48 hours

Conclusion/Summary : Not available

Persistence/degradability

Conclusion/Summary : Not available.

Canada

5/9

Aquatic ecotoxicity

Product/ingredient name	Result	Species	Exposure
Copper(II) sulfate, pentahydrate (1:1:5)	EC50 0.024 mg/l	Daphnia	48 hours

Conclusion/Summary : Not available

Persistence/degradability

Conclusion/Summary : Not available.

Other adverse effects : No known significant effects or critical hazards.

2/29/2012.

6/9

www.thermo.com

Life Science Research PO Rox 117

Rockford, IL (815) 968-0747 Pierce Biotechnology Inc. 3747 N. Meridian Road (815) 968-7316 Fax

13. Disposal considerations

Waste disposal

: The generation of waste should be avoided or minimized wherever possible. Significant quantities of waste product residues should not be disposed of via the foul sewer but processed in a suitable effluent treatment plant. Dispose of surplus and non-recyclable products via a licensed waste disposal contractor. Disposal of this product, solutions and any by-products should at all times comply with the requirements of environmental protection and waste disposal legislation and any regional local authority requirements. Waste packaging should be recycled. Incineration or landfill should only be considered when recycling is not feasible. This material and its container must be disposed of in a safe way. Care should be taken when handling emptied containers that have not been cleaned or rinsed out. Empty containers or liners may retain some product residues. Avoid dispersal of spilled material and runoff and contact with soil, waterways, drains and sewers.

Disposal should be in accordance with applicable regional, national and local laws and regulations. Refer to Section 7: HANDLING AND STORAGE and Section 8: EXPOSURE CONTROLS/PERSONAL PROTECTION for additional handling information and protection of employees.

14. Transport information

Regulatory information	UN number	Proper shipping name	Classes	PG*
DOT Classification	UN3082	Environmentally Hazardous Substance, Liquid, n.o.s. (Copper(II) sulfate, pentahydrate (1:1:5), solution). Marine pollutant (Copper(II) sulfate, pentahydrate (1:1:5))	9	≡
IATA-DGR Class	UN3082	Environmentally Hazardous Substance, Liquid, n.o.s. (Copper (II) sulfate, pentahydrate (1:1:5))	9	III

PG* : Packing group

15. Regulatory information

United States

2/29/2012.

HCS Classification

: Toxic material Irritating material Sensitizing material Target organ effects

U.S. Federal regulations

TSCA 8(a) IUR Exempt/Partial exemption: Not determined

United States inventory (TSCA 8b): All components are listed or exempted.

SARA 302/304/311/312 extremely hazardous substances: No products were found. SARA 302/304 emergency planning and notification: No products were found. SARA 302/304/311/312 hazardous chemicals: Copper(II) sulfate, pentahydrate (1:1:5) SARA 311/312 MSDS distribution - chemical inventory - hazard identification: Copper(II) sulfate, pentahydrate (1:1:5): Immediate (acuté) health hazard, Delayed

www.thermo.com

(chronic) health hazard

Clean Water Act (CWA) 307: Copper(II) sulfate, pentahydrate (1:1:5)

Pierce® BCA Reagents

15. Regulatory information

Clean Air Act Section 112(b) Hazardous Air

: Not listed

Pollutants (HAPs)

Clean Air Act Section 602 : Not listed

Class I Substances

Clean Air Act Section 602 : Not listed

Class II Substances

DEA List I Chemicals : Not listed

(Precursor Chemicals) **DEA List II Chemicals**

: Not listed

(Essential Chemicals)

SARA 313

	Product name	CAS number	Concentration
Form R - Reporting requirements	Copper(II) sulfate, pentahydrate (1:1:5)	7758-99-8	3 - 5

SARA 313 notifications must not be detached from the MSDS and any copying and redistribution of the MSDS shall include copying and redistribution of the notice attached to copies of the MSDS subsequently redistributed.

State regulations

Massachusetts : The following components are listed: Copper(II) sulfate, pentahydrate (1:1:5)

New York : None of the components are listed.

New Jersey : The following components are listed: COPPER compounds Pennsylvania : The following components are listed: COPPER COMPOUNDS

United States inventory : All components are listed or exempted.

(TSCA 8b)

Canada

WHMIS (Canada) : Class D-2B: Material causing other toxic effects (Toxic).

Canadian lists

Canadian NPRI : The following components are listed: Copper **CEPA Toxic substances** : None of the components are listed. Canada inventory : All components are listed or exempted.

This product has been classified in accordance with the hazard criteria of the Controlled Products Regulations and the MSDS contains all the information required by the Controlled Products Regulations.

International regulations

International lists : Australia inventory (AICS): All components are listed or exempted.

> China inventory (IECSC): All components are listed or exempted. Japan inventory: All components are listed or exempted. Korea inventory: All components are listed or exempted.

New Zealand Inventory of Chemicals (NZIoC): All components are listed or exempted.

Philippines inventory (PICCS): All components are listed or exempted.

16. Other information

Label requirements

HARMFUL IF SWALLOWED. CAUSES RESPIRATORY TRACT, EYE AND SKIN IRRITATION. MAY CAUSE ALLERGIC SKIN REACTION. CONTAINS MATERIAL

THAT CAN CAUSE TARGET ORGAN DAMAGE.

Hazardous Material Information System (U.S.A.)



2/29/2012. 8/9

7/9

16. Other information



The customer is responsible for determining the PPE code for this material.

National Fire Protection Association (U.S.A.)



 Date of printing
 : 2/29/2012.

 Date of issue
 : 2/29/2012.

 Date of previous issue
 : 8/8/2011.

 Version
 : 1.02

Prepared by : MSDS Specialist

▼Indicates information that has changed from previously issued version.

Notice to reader

To the best of our knowledge, the information contained herein is accurate. However, neither the above-named supplier, nor any of its subsidiaries, assumes any liability whatsoever for the accuracy or completeness of the information contained herein.

Final determination of suitability of any material is the sole responsibility of the user. All materials may present unknown hazards and should be used with caution. Although certain hazards are described herein, we cannot guarantee that these are the only hazards that exist.

2/29/2012. 9/9

Life Science Research PO Box 117 Rockford, IL (815) 968-0747 www.thermo.com Pierce Biotechnology Inc. 3747 N. Meridian Road 61105 (815) 968-7316 Fax

